

ASSEMBLY INSTRUCTION


MELFORT EXTENSION










Note: Improper use, improper assembly and mishandling may lead to defects/ cracks appearing.









Storage

